


CSAT3 Packing Information

The CSAT3 components are placed in a foam cutout that helps protect them from damage during shipment. The CSAT3 should look like the picture below. After unpacking, it is recommended to save the foam cutout as the CSAT3 components should be placed in the foam cutout whenever the CSAT3 is transported to another location.

Place the CSAT3 electronics box in the cutout, with the text facing up, and the connectors pointing away from the center of the case.



Neatly coil and store the CSAT3 head cable. Make sure the cable will not be pinched when the case lid is closed.

Place the CSAT3 head into the bottom half of the case, with the text side facing up.

Underneath the circular foam cutout are the following items:

- (2) #17492 U-bolts with Nuts
- (4) #4365 Washers
- (2) #9786 Tension Brackets
- (1) CM250 Leveling Mounting Kit
- (1) Analog Output Cable, 25 ft
- (1) RS-232 Output Cable, 25 ft
- (1) Power/SDM Cable, 25 ft

